

**SN: 101-0118**

# **Bridge Condition Report**


**DISTRICT:** 2

**ROUTE:** FAS 40 (Prairie Hill Road)

**SECTION:** 133-B-CF

**COUNTY:** Winnebago

**STRUCTURE NUMBER:** 101-0118 (EXISTING)



**LOCATION:** Prairie Hill Rd. over Rock River  
(0.4 miles West of IL. 2).

**PREPARED BY:** Kenneth S. Couperus

**DATE PREPARED:** November 2008

**PROPOSED LETTING DATE:** PY 2011



## **TABLE OF CONTENTS**

<b>Item:</b>	<b>Page:</b>
I. Geographical & Administrative Data	1
II. Physical Description of Structure	1, 2
III. Field Inspection & Physical Evaluation	2, 3
IV. Potential Scope of Work Determination & Analysis	3
V. Discussion and Recommended Scope of Work	3, 4
 <b><u>Attachments:</u></b>	 4
A. Location Map	
B. IDOT Master Structure Report	
C. Bridge Inspection Report	
D. PONTIS Inspection Report	
E. 2008 Deck Surface Survey & Section Loss Measurements	
F. Structure Photos	
G. Original plans and proposed scour countermeasures plans	
H. Cost Estimates	

## **I. Geographical & Administrative Data:**

**Structure Number:** 101-0118  
**County:** Winnebago  
**Route Carried:** Prairie Hill Road  
**Feature Crossed:** Rock River  
**Section:** 133-B-CF  
**Station:** 65+47.50

**Roadway Classification:** Minor Arterial, (Urban)  
**Design/Posted Speed:** 45 MPH/ 45 MPH  
**ADT (current/future):** 2004 (5200) / 2026 (9400)  
**ADTT (current/future):** 2004 (104) / 2026(188)  
**DHV:** 520  
**Inventory Rating HS:** 17.8  
**Operating Rating HS:** 30.6  
**Sufficiency Rating:** 60.8

## **Construction / Reconstruction / Repair History:**

**Construction:** The original structure was built in **1966** as a five span continuous steel wide flange under Section 133-B-CF with **HS20-44** design loading.

**Bridge Deck Repairs:** Partial and full depth patching was performed by state forces in various years.

**Substructure Repairs:** A contract to install scour countermeasures is pending at an estimated cost of \$300,000.00. CN 64D71 Section (133-B-CF)M.

## **II. Physical Description of Structure:**

Structure 101-0118 is a five span continuous wide flange beam superstructure with 6 beam lines (36WF150) on two open reinforced concrete stub abutments founded on concrete batter piles and four reinforced concrete solid wall style piers founded on spread footings with 22 degree left ahead skew angle. The continuous beams are fixed at pier 3 and expansion over piers 1, 2, 4 and the abutments. Note: The piers are numbered from north to south which is opposite of convention.

The deck is 7 inches thick with no overlay and has no deck protection.

There are welded cover plates over each pier.

The beams sit on steel rocker bearings on both the piers and the abutments.

The joint at the East abutment is an open joint (2 angle irons with no fill) and the joint at the West abutment is a sliding plate joint.

The back-to-back of abutment length is 420 ft-6in and the span lengths are 91 ft (spans 2, 3 and 4), 71 ft (spans 1 & 5). The out-to-out deck width is 36ft.

The structure provides for one 12 ft traffic lane in each direction with 2 ft raised concrete sidewalks on each side. The structure is 30 ft-0 in. wide face to face of curbs. The railing consists of a single aluminum pipe mounted on concrete parapet wall.

The existing structure is located on tangent horizontally but vertically slopes from west to east on about a 3.9% grade. The approach roadway templates at both ends are the same; 2-12 ft lanes with 4 ft aggregate shoulders.

The slope walls consist of 6 in thick concrete.

### **III. Field Inspection & Physical Evaluation:**

**Deck:** The deck is **42** years old and in **poor** condition. A visual/chain drag deck surface survey conducted at the time of this BCR revealed that 64% of the deck was cracked, delaminated or spalled (See survey in attachments). The water table (portion of deck soffitt that overhangs the fascias) has numerous areas with leaching, map cracking and wetness. The soffitt areas around the deck drains exhibit wetness, discoloration and small spalls. Note: The spacing of the drains is every 6 ft for the full length of the bridge on both sides. There is approximately 17 SF of full depth patching. The deck surface is contaminated with numerous large and small spalls filled with bituminous concrete and there are numerous small to medium transverse cracks at less than 5 ft intervals throughout. There is no deck protection provided. Many drain extensions are missing.

The bridge rail and transitions are substandard.

The open joint at the east abutment (low end of the structure) has caused heavy deterioration to the bearings, beam ends, diaphragms and abutment at the East end. The sliding plate joint at the west abutment leaks heavily and is spalled along the entire length. Note: The fixed plate portion has been removed.

**Superstructure:** The superstructure is **42** years old and in **fair** condition. The original paint system is failing throughout. At the East end the beam ends and end diaphragms exhibit heavy corrosion, lamination and initial section loss (less than 10%) with the West end being very similar but not quite as bad. See photos and section loss measurements in the attachments. No cracks were found in a random sample of cover plate ends. At many drain locations (every 6 ft) the top and bottom flanges are more heavily corroded due to missing drain extensions. There is a lot of graffiti at both ends.

**Substructure:** The substructure is **42** years old and in **satisfactory** condition. Concrete in the substructure is generally sound. The abutments are wet most of the time due to leaking joints and exhibit some large spalling with exposed rebar to the abutment caps. The back walls are discolored and contain some small to medium vertical and horizontal cracking and some small spalls.

The piers are in good condition with map cracking and leaching at the cap nose of pier 1 at the North end. There are no joints over piers. The piers are founded on spread footings (scour

critical rating-3) and local minor scour holes were found on Piers 1, 2 and 4 during the last underwater inspection.

Some areas of the slope walls have been undermined by erosion and exhibit movement.

The rocker bearings at the abutments are heavily corroded and are likely frozen in place.

#### **Inspection History (NBIS Ratings):**

<b>Year</b>	<b>Deck (58)</b>	<b>Super (59)</b>	<b>Sub (60)</b>
2008	4	5	6
2006	4	5	6
2004	4	5	6
2002	4	5	6
2000	4	5	6
1998	5	6	6
1997	5	6	4
1996	6	6	4

#### **Geometric/Hydraulic Data:**

The structural evaluation is rated a 5-Better than adequate to be left in place, the deck geometry is rated a 4-Minimum adequacy to be left in place. The scour critical rating is a 3-Unstable for calculated scour by computer calculation. The piers are on spread footings. Note: Proposed bridge cross section to be determined by others. If option 2 or 3 is chosen a formal Hydraulic Report will be required-to be prepared by others.

### **IV. Potential Scope of Work Determination & Analysis:**

**Option 1:** Rehabilitation-Deck Replacement, New End Diaphragms, Plate Beam Ends and Superstructure Painting: Remove and replace deck, install new end diaphragms, plate all beam ends (12) and paint entire superstructure.

**Option 2:** Superstructure Replacement: Place new steel superstructure and replace existing rocker bearings with elastomeric bearings.

**Option 3:** Total Structure Replacement:

### **V. Discussion and Recommended Scope of Work:**

The Deck is in poor condition, is 42 years old and will need replaced. The ADTT is only 104 (2004) which is well below the required limits (1500) to perform a fatigue evaluation and because no cracks were observed at the cover plate ends the existing welded cover plates are not eligible for retrofit. The deck is programmed for replacement in 2011. Also, the inventory rating is 17.8 (<20).

Although minor section loss was found at 8 of 12 beam ends it is believed that by the time this structure is rehabilitated (2 more years?) the section loss would warrant plating the beam ends at a minimum. At the time of this BCR preparation the end diaphragms had medium to heavy corrosion on the expansion joint side and replacement will be included in the cost estimate for Option 1. Note: if option 1 is chosen the existing rocker style bearings will remain in place.

The cost estimate for option 1 amounted to \$1,484,172.00 which is greater than 60% (67.7%) the cost of total replacement (\$2,195,010.00). Option 2 is also greater than 60% (72.2%) of total replacement.

Based on the cost analysis the most economical option is option 1-Deck replacement with new end diaphragms, plate beam ends and paint entire superstructure, however due to the substructure problems with spread footings founded on scour critical soils, the fact that the scour countermeasures contract has not been awarded (and will not be if option 3 is chosen) and the policy that if any major rehabilitation is greater than 60% the cost of a new structure we believe the best course of action would be option 3-Total Replacement.

Traffic Control: Closing the bridge and detouring traffic would be the preferred staging method if an acceptable detour route can be found. (To be determined by Others.).


#### **ATTACHMENTS:**

- |               |   |
|---------------|---|
| Attachment A: | Location map  |
| Attachment B: | IDOT Master Structure Report                            |
| Attachment C: | Bridge Inspection Report                                |
| Attachment D: | PONTIS Inspection Report                                |
| Attachment E: | 2008 Deck Surface Survey & Section Loss Measurements    |
| Attachment F: | Structure Photos  |
| Attachment G: | Original plans and proposed scour countermeasures plans |
| Attachment H: | Cost Estimates  |

# **Attachment A:**

# **Location Map**





# **LOCATION MAP**

for

**FAU ROUTE 9876 (PRAIRIE HILL ROAD)**

**SECTION (133B-CF)D**

**WINNIBAGO COUNTY**

**JOB NO. P-92-107-08**

**Attachment B:**

**IDOT Master Structure Report**

**Illinois Department of Transportation  
Structures Information Management System  
Master Structure Report (S-107)**

Structure Number: 101-0118 District: 2

**Inventory Data**

Facility Carried:	PRAIRIE HILL ROAD	Bridge Name:		Sufficiency Rating:	60.8	Structure Length:	420.5
Feature Crossed:	ROCK RIVER	Location:	0.4 MI W ILL 2	HBRRP Eligible:	Yes	AASHTO Bridge Length:	99.9
Bridge Remarks:				Replaced By:	000-0000	Length of Long Span:	91.0
Bridge Status:	1 OPEN - NO RESTRICT	Status Date:	04/1988	Replaces:	000-0000	Bridge Roadway Width:	30.0
Status Remarks:				Last Update Date:	08/11/2008	Appr Roadway Width:	44.0
Maint County:	101 WINNEBAGO	Maint Township:	10 ROCKTON	Parallel Structure:	None	Deck Width:	36.1
Maint Responsibility:	01 I.D.O.T.			Multi-Level Structure Nbr:		Sidewalk Width Right:	2.0
Service On/Under:	1 HIGHWAY		5 WATERWAY	Skew Direction:	Left	Sidewalk Width Left:	2.0
Reporting Agency:	1 I.D.O.T. - BUREAU OF MAINTENANCE			Skew Angle:	22 D 00 M 00 S	Navigation Control:	0 No
Main Span Matl/Type:	4 STEEL CONTINUOUS		02 STRINGER/MULTI-BEAM/GIRDER	Structure Flared:	No	Navigation Horiz Clear:	0
Nbr Of Main Spans:	5	Nbr Of Approach Spans:	0	Historical Significance:	No	Navigation Vert Clear:	0

**\*\*\*Approaches\*\*\***

Near #1 Matl/Type:				Rated By:	2 IDOT	Rate Method:	2 ALLOWABLE STRESS
Near #2 Matl/Type:				Inventory Rating:	17.8 (232)	Load Rating Date:	05/03/1994
Far #1 Matl/Type:				Operating Rating:	30.6 (255)		
Far #2 Matl/Type:				Design Load:	02 HS20		

Median Width/Type:	0 Ft / 0 None				
Guardrail Type L/R:	0 None	/	0 None		
Toll Facility Indicator:	0 No Toll				
Latitude:	42 D 28 M	32.44 S	Longitude:	89 D 03 M	50.44 S
Deck Structure Type:	A	CIP CON NORMALLY FORM	Deck Structure Thickness:	7.0	
Sidewalks Under Structure:	0	None			

**Key Route On Data**

Key Route Nbr:	FEDERAL-AID URBAN	Station:	000.180
Appurtenances	Main Route	Segment:	
Inventory County:	101 WINNEBAGO	Linked:	Y
Township/Road Dist	10 ROCKTON	Natl. Hwy System:	
Municipality	0000	Inventory Direction:	
Urban Area:	5400	Curr AADT Yr/Count:	
Functional Class:	70 MINOR ARTERIAL (URBAN)	Est Truck Percentage:	
** CLEARANCES **	South/East	Number Of Lanes:	
Max Rdwy Width:	030.0	One Or Two Way:	
Horizontal:	034.0	Bypass Length:	
Min Vertical:	99 Ft 11 In	Future AADT Yr/Cnt:	
10 Ft Vertical:	99 Ft 11 In	Designated Truck Rte:	
Lateral:		Special Systems:	

**Key Route Under Data**

Station:	
Segment:	
Linked:	
Natl. Hwy System:	
Inventory Direction:	
Curr AADT Yr/Count:	
Est Truck Percentage:	
Number Of Lanes:	
One Or Two Way:	
Bypass Length:	
Future AADT Yr/Cnt:	
Designated Truck Rte:	
Special Systems:	

**\*\*\*Marked Route On Data\*\*\***

Route #1:	1 Mainline	Designation	8 Other	Kind		Number	9876
Route #2:							
Route #3:							

**\*\*\*Marked Route Under Data\*\*\***

Designation		Kind		Number	

**Illinois Department of Transportation  
Structures Information Management System  
Master Structure Report (S-107)**

Structure Number: 101-0118 District: 2

**Data Related to Inspection Information**

## \*\*\*Inspection Intervals \*\*\*

 Routine NBIS: 24 MOS Underwater: 24 MOS One Truck At A Time: 24 MOS  
 Fracture Critical: 0 MOS Special: 0 MOS Single Unit Vehicles: 0 MOS

## \*\*\* Maximum Allowable Posting Limits \*\*\*

 Combination Type 3S-1: 0 Tons  
 Combination Type 3S-2: 0 Tons

## Bridge Posting Level:

5 No Posting Required

**Inspection/Appraisal Information**

Inspection Date: 07/31/2008 Inspection Temperature: 80 Deg. F  
 Deck: 4 POOR CONDITION - ADVANCED DETERIORATION  
 Superstructure: 5 FAIR CONDITION - MINOR SECTION LOSS, CRACKS  
 Substructure: 6 SATISFACTORY CONDITION - MINOR DETERIORATION  
 Culvert: N NOT APPLICABLE  
 Channel and Protection: 7 GOOD CONDITION - SOME MINOR PROBLEMS  
 Structural Evaluation: 5 BETTER THAN ADEQUATE TO BE LEFT IN PLACE  
 Deck Geometry: 4 MINIMUM ADEQUACY TO BE LEFT IN PLACE  
 Underclearance-Vert/Lat.: N NOT APPLICABLE  
 Waterway Adequacy: 8 EQUAL TO PRESENT DESIRABLE CRITERIA  
 Approach Roadway Align: 8 EQUAL TO PRESENT DESIRABLE CRITERIA  
 Bridge Railing Appraisal: 2 Doesn't Meet Standards  
 Approach Guardrail: 122 Does Not Exist Not Acceptable  
 Pier Navig Protection: N N/A

Insp by (Name): COUPERUSKS  
 Insp by (Name): LINKDJ  
 Utilities Attached: N N/A  
 N N/A  
 N N/A  
 A BARE DECK NO OVRLAY  
 F NONE  
 J NONE  
 07.0  
 06/1965

\*\* Actual Posted Limits \*\*  
 Single Unit Vehicles: 0 Tons  
 Combination Type 3S-1: 0 Tons  
 Combination Type 3S-2: 0 Tons  
 One Truck At A Time: 0 Tons  
 Last Paint Type: B  
 LD SHP PRM AL FNL

Deck Wearing Surf: A  
 Deck Membrane: F  
 Deck Protection: J  
 Total Deck Thick: 07.0  
 Last Paint Date: 06/1965

Inspection Remarks:  
 58) NUMEROUS PD & FD PATCHES & LARGE AREAS OF DELAMINATIONS. 60) DUE TO LOCAL M MINOR SCOUR HOLES. 59) DUE TO MINOR SECTION LOSS AT BM ENDS. BEARINGS AT ABOUT S. HEAVILY LAMINATED, JOINTS LEAK HEAVILY, DIAPHRAGMS AT ABUTTS HEAVILY CORRODED

**Underwater Inspection/Appraisal Information**

Inspection Date: 07/31/2008 Inspection Category: 1246 Debris problem  
 Temperature: 80 Inspection Method: S Sonar  
 Inspected By: COUPERUSKS Inspected By: LINKDJ Appraisal Rating: 6 FAIR CONDITION - MAJOR REPAIR POSSIBLE  
 Inspection Remarks: PIERS ON SPREAD FOOTINGS. SONAR RUN ON ALL PIER FACES-WORST CASE WAS P2 W FACE E W/5FT COVER. MINOR LOCAL SCOUR HOLES FOUND ON P1,2 & 4. SEE SONAR TAPE IN FILE.

**Scour Critical Information**

Rating: 3 CRITICAL - UNSTABLE FOR CALCULATED SCOUR Evaluation Method: A Computer Calculation  
 Analysis Date: 05/25/1992 Analysis By: TRJ

**Miscellaneous**

Fracture Critical Members: No  
 Microfilm Data Recorded: Yes

**Construction Information**

Year: 1966 Original  
 Route: CH 76 Sta: 65+47.50  
 Section Nbr: 133-B-CF  
 Contract Nbr: 0000000000000000  
 Fed Aid Pr #: 3 COUNTY AGENCY  
 Built By:

Flood Design Frequency: 0 YRS Drainage Area: 0 Acre  
 Flood Design Q (CFS): 0  
 Flood Design Nat H W E: 0  
 Flood Des Open Prop: 0 SF Flood Base Nat H W E: 0

**Proposed Improvement**

Cost Estimate Year: 1998 Length: 421  
 Type of Work: 35 REHABILITATION DUE TO GENERAL DETERIORATION  
 Done By: 1 Contract  
 Remarks:

\*\*\* Costs in Dollars \*\*\*  
 Bridge Cost: 1,093  
 Roadway Cost: 109  
 Total Project Cost: 1,640

**Attachment C:**

**Bridge Inspection Report**



**Structure Number: 101-0118**

**Location & Inventory Information**

Maint. Co: WINNEBAGO Twsp: ROCKTON Status: OPEN - NO RESTRICT  
 Facility Carried: PRAIRIE HILL ROAD Feature Crossed: ROCK RIVER Team/Sub  
 Location: 0.4 MI W ILL 2 Municipality:  Section  
 234 / 906  
 Total # Spans: 5 Material: STEEL CONTINUOUS Type: STRINGER/MULTI-BEAM/GIRDER  
 Inspection Intervals (Mo.): Routine NBIS 24 / Fracture Critical 0 / Underwater - 24

90 - Inspection Date: / / 90C - Temp. (°F):  93C - Special Inspection Date: / /  
 90A - Inspection Team Leader:  Qualification:

**Inspector's Appraisals**

	Prev	New		Prev	New		Prev	New
58 - Deck Condition:	4		62 - Culvert Condition:	N		72 - Approach Rdwy Align:	8	
59 - Superstructure Cond:	5		61 - Channel Condition:	7		111 - Pier Navig Protection:	N	
60 - Substructure Cond:	6		71 - Waterway Adequacy:	8		Appraisal Comments: <u></u>		

**Additional Inspection Data**

	Prev	New		Prev	New		Prev	New
36A - Bridge Railing Adequacy:	2		36B - Transitions:	1		36C - Guardrail:	2	
Approach Guardrail Adequacy:						36D - Ends:	2	

Railing  
Comments:

	Prev	New		Prev	New		Prev	New
108A - Wearing Surface Type:	A		108B - Type of Membrane:	F		108C - Deck Protection:	J	
108D - Total Deck Thickness (In.):	07.0		Deck Comments: <u></u>					

	Prev	New		Prev	New
59A - Paint Date (Mo/Yr):	06/1965	/	59B - Paint Systems:	B	
			Paint Comments: <u></u>		
			Color: Fascia - <u></u> ; Inter. - <u></u> ; Railing - <u></u> .		

	Prev	New		Prev	New
59C - Utilities Attached:	NNN		Utilities Comments: <u></u>		

	Prev	New		Prev	New
Weight Limit Posting:			70A2 - Single Unit Vehicles:		T.
			Combination Vehicles: 70B2 - 3 or 4 Axles:		T.
			70C2 - 5 or More Axles:		T.
			70D2 - One Truck at a Time:		
			Posting Comments: <u></u>		

**90B - Inspection Remarks:** (Note: 237 characters maximum)

Previous Inspection	Remarks
	58) NUMEROUS PD & FD PATCHES & LARGE AREAS OF DELAMINATIONS. 60) DUE TO LOCAL MINOR SCOUR HOLES. 59) DUE TO MINOR SECTION LOSS AT BM ENDS. BEARINGS AT ABUTS. HEAVILY LAMINATED, JOINTS LEAK HEAVILY, DIAPHRAMS AT ABUTS HEAVILY CORRODED.
New Inspection	

	Signature	Date	Supervisor Init. & Date
Inspection Team Leader:		/ /	



## Underwater Field Inspection Report

SN: 1010118 District: 2 Spans: 5 Appr. Spans: 0 Skew: 22 ADT: 5200 Truck Pct: 2 ADT Un: 0

Facility Carried: PRAIRIE HILL ROAD

Name:

Feature Crossed: ROCK RIVER

Location: 0.4 MI W ILL 2

Inspection Date: 07/31/2008

Inspection Notes: 58) NUMEROUS PD & FD PATCHES & LARGE AREAS OF DELAMINATIONS. 60) DUE TO LOCAL MINOR SCOUR HOLES. 59) DUE TO MINOR SECTION LOSS AT BM ENDS. BEARINGS AT ABUTS. HEAVILY LAMINATED, JOINTS LEAK HEAVILY, DIAPHRAGMS AT ABUTS HEAVILY CORRODED.

Inspector 1: COUPERUSKS

Temp: 80

Inspector 2: LINKDJ

### Resources

Time to Insp: 03:00

Trffc Ctrl: 1

Boat: B

Waders:

Snooper:

Ladder:

Manlift:

Other: sonar

### Inspector's Appraisals

93B5-Category(s): 1246

Insp Substructure: PIERS 1-4

93B1-Rating: 

Prev	New
6	

93B4-Method: 

Prev	New
S	

 V: ☐ P: ☐ S: ☐ D: ☐ O: ☐

93B2-Remarks: PIERS ON SPREAD FOOTINGS. SONAR RUN ON ALL PIER FACES-WORST CASE WAS P2 W FACEE W/5FT COVER. MINOR LOCAL SCOUR HOLES FOUND ON P1,2 & 4. SEE SONAR TAPE IN FILE.

Remarks:

Inspected By: \_\_\_\_\_

**Attachment D:**

**PONTIS Inspection Report**





## Element Level Field Inspection Report

SN: 1010118 District: 2 Spans: 5 Appr. Spans: 0 Skew: 22 ADT: 5200 Truck Pct: 2 ADT Un: 0

Facility Carried: PRAIRIE HILL ROAD

Name:

Feature Crossed: ROCK RIVER

Location: 0.4 MI W ILL 2

Inspection Date: 11/18/2008

Inspection Notes: Heavy spalling and numerous trans cracking. Updated for BCR preparation...

Inspector 1: COUPERUSKS

Inspector 2:

Temp: 45

### Resources

Time to Insp:	01:00	Trffc Ctrl:	1	Boat:		Waders:		Snooper:	
		Ladder:		Manlift:		Other:			

### Inspector's Appraisals

Elem	Element Desc	Env	Quantity	Un	CS1	CS2	CS3	CS4	CS5
12	Concrete Deck Bare	3	15009	SF	5359	0	9650	0	0
Remarks: Heavy spalling and numerous trans cracking. Updated for BCR preparation...									
107	Lead Painted Steel Open Girder	1	26000	SF	10000	5400	10600	0	0
Remarks:									
172	Lead Painted Steel Closed Web/Box Girder and Open	3	12	EA	0	1	3	8	0
Remarks:									
210	Reinforced Conc Pier Wall	1	5760	SF	5760	0	0	0	0
Remarks:									
215	Reinforced Conc Abutment	1	677	SF	577	0	100	0	0
Remarks:									
234	Reinforced Conc Pier or Abutment Cap	1	232	LF	200	12	20	0	0
Remarks: @ P1 cap.									



## Element Level Field Inspection Report

SN: 1010118 District: 2 Spans: 5 Appr. Spans: 0 Skew: 22 ADT: 5200 Truck Pct: 2 ADT Un: 0

302	Preformed Joint Seal	3	33	LF	0	0	33	0	0
Remarks:		At W end-this is actually a sliding plate joint-no PONTIS element for this.							
304	Open Expansion Joint	3	33	LF	0	33	0	0	0
Remarks:		At E end.							
311	Movable Discontinuous Brg.	3	12	EA	0	4	8	0	0
Remarks:									
313	Fixed Bearing	3	6	EA	6	0	0	0	0
Remarks:									
316	Moveable Steel Bearings below continuous decks	3	18	EA	18	0	0	0	0
Remarks:									
323	Approach Pavement	3	2	EA	2	0	0	0	0
Remarks:									
331	Concrete Bridge Railing	3	834	LF	834	0	0	0	0
Remarks:									

Inspected By: \_\_\_\_\_